



Lineman Tech Center

Needs for Phases 1 and 2

Lineman Tech Center

Somerset Community College

Eye nuts [5/8]

Voltage Regulators

C-meter

Load break Cutouts

Transformer leads [copper wire]

Transformers

[3 conventional--15 kw or smaller no oil-
none working for banking]

[6 pole mount-smaller size- working]

Padmount Transformers

Spade connectors [banking]

Triplex and Quad 20'-30' pieces [smaller sizes]

Wire Preform dead ends

Live Line Tools

Disconnects- underarm and in line

Training Videos on all aspects of line work

Preformed dead end grips all wire size.

Single and Three Phase Meters

Meter bases Single and Three Phase

Instrument Meter Cabinet

Instrument Meter and Base

Conduit & pole att. Brackets

Line fuses {low amperage}

½ inch poly 3 braid rope {handlines}

Stringing rope

#6 and #4 alum tie wire

Dead-end assemblies {bells, polymer strain
insulators, unitary}

Dead end shoes and angle shoes [#2 acsr]

#4 or #2 acsr

Guy wire and performs

Wire clevis [swinging and wide back]

DA bolts [22" and up]

10-12-14 inch machine bolts [5/8]

10-12-14 inch eye bolts [5/8]

UG service Connectors [bolts also]

#4 copper [butt grounds]

#4 copper poly [transformer high side]

Saddles, stirrups, bird swings

Bolted connectors [2 bolt, split bolts, 4 bolts]

4' or 6' anchor rods and expand anchors

C-hooks --Transmission bells to arm
attachment

If you would like to donate any of these items, please contact Dean Rhodes with your donation. We will keep the list updated as items are donated.

Thank you in advance for you donations to the Lineman Tech Center

Contact information:

Dean Rhodes

606-451-6699 or cell 606-875-1890

Dean.rhodes@kctcs.edu

